

補修後(H23.5.18)



排気第11系統ダクト接続部(H23.3.11)




(H23.3.11)



補修後(H23.5.18)




(H23.3.11)



使-01~2

プルトニウム研究1棟105号室排気第11系統ダクト配管落下




使-01~3 プルトニウム研究1棟102号室排気第4系統ギャラリ破損

震災後(H23.5.16)



修理後(H24.8.16)



使-01~4 プルトニウム研究1棟104号室排気第4系統吸込ギャリ亀裂

震災後(H23.5.16)




修理後(H24.8.16)



震災後(H23.5.16)



修理後(H24.8.16)



震災後(H23.5.16)



修理後(H24.8.16)




使-01~5

プルトニウム研究1棟106号室排気第11系統ダクト破損

震災後(H23.5.16)



修理後(H24.8.16)



使-01～6 プルトニウム研究1棟107号室排気第10系統ダクト接続箇所への亀裂

202号室 排気第8系統ダクト亀裂

震災後(H23.4.11)



震災後(H23.4.11)



修理後(H24.8.16)



修理後(H24.8.16)





202号室 排気第9系統防火ダンパのずれ

震災後(H23.4.11)



修理後(H24.8.16)





使-01~1 プルトニウム研究1棟108号室排気第8系統、排気第10系統ダクト配管亀裂