




補修前



補修後(H24.2.28)



補修前



補修後(H24.2.28)

使-30

第4研究棟 排水管の破損